

Certificate of Conformity of Factory Production Control

This certificate is issued to:

Manufacturer:

ACEBRON GROUP

Pol. Ind. Penapurreira C/ Toxo verde, Parcela A-2 C.P.15320 As Pontes (A Coruña), España

In compliance with *Regulation 305/2011/EU of the European Parliament and of the Council of 9 March 2011* (the Construction Products Regulation or CPR), this certificate applies to the construction product:

Execution of steel structural components up to EXC3

This certificate attests that all provisions concerning the assessment and verification of constancy of performance and the performances described in Annex ZA of the standard(s)

EN 1090-1:2009+A1:2011 Execution of Steel Structures and Aluminium Structures - Part 1: Requirements for conformity assessment of structural components

under system 2+, are applied and that the factory production control is assessed to be in conformity with the applicable requirements.

The attached Schedule, of the same date, details the manufacturing location(s), harmonised product standard and product parameters and shall form a part of this certificate.

This Certificate will remain valid as long as the test methods and/or factory production control requirements included in the harmonised standard, used to assess the performance of the declared characteristics, do not change, and the product, and the manufacturing conditions in the plant are not modified significantly.

Certificate No:	0094/CPR/MAD/20170149 ENG	LRQA
Original Approval:	31 December 2020	LRQA
Current Certificate: Certificate expiry date 24 August 2023 validity extended till 31	2 November 2023	LINGIA
Expiry Date:	24 August 2026	LRQA
LRQA Inspection Iberia, S.A. Notified Body 0094		

Juan Antonio Pozo LRQA Decision maker



LRQA Inspection Iberia, S.A. is a company registered in the R. M. de Madrid, in Volume 5218 general, 4358, of Section Sec. 3.^a of the Companies Book, folio 133 sheet nº 41397, inscription. 1.^a C.I.F. - A28591287 - Registered office C/Princesa 29, 1º, 28008 Madrid. A subsidiary of LRQA Group Limited.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

-	1		
	. 69	17.	
1.3	~		

.RQ/\



Manufacturer:

Certificate of Conformity of Factory Production Control
No.: 0094/CPR/ MAD/20170149 ENG Schedule

.RQ/\

LRQ/\

Pol. Ind. Penapurreira C/ Toxo verde, Parcela A-2. C.P.15320 As Pontes (A Coruña), España

GRUPO ACEBRON

	1		IDOA
Manufacturing plant		anizados Acebrón S.L.U.	LRQA
	 (MECACE) Pol. Ind. Penapurreira,C/ Toxo verde, Parcela A-2 15320 As Pontes (A Coruña). Pol Ind. Penapurreira C/ Barosa , Parcela A-8 , 15320 As Pontes (A Coruña). 		
Product	Product standards		
Execution of steel structural components	EN 1090-1:2009+ A1:2011 EN 1090-2:2018		
Production Range			LRQA
Cold cutting, holing/drilling and shaping/forming.			
Exclusions			
Design, mechanical fastening and welding			LRQA
Parent material group (ISO/TR 15608):	Welding process (ISO 4063)		
NA	NA		LRQ/\
CE marking method: 3a	Execution class:	EXC3	
			LRQ/\
Manufacturing plant	Talleres Acesan, S.	L.U. (ACESAN)	
	Pol. Ind. Penapurreira, C/ Barosa, Parcela A-9.1 -		
	15320 As Pontes (A Coruña)		
Product	Product standard		
Execution of steel structural components	EN 1090-1:2009+ A1:2011		LRQ/\
	EN 1090-2:2018		
Production Range			
Thermal and cold cutting, shaping/forming,			LRQ/\
holing/drilling, heat treatment , welding and			
corrosion protection			LRQ/\
Exclusions			
Design, mechanical fastening			
Parent material group (ISO/TR 15608):	Welding process (I	SO 4063)	LRQA
roups: 1.1, 1.2 & 1.3 (Yield Strength ≤ 460 N/mm ²) . 8.1 121, 135, 136, 138 & 141			
			LRQA



LRQA Inspection Iberia, S.A. is a company registered in the R. M. de Madrid, in Volume 5218 general, 4358, of Section Sec. 3.^a of the Companies Book, folio 133 sheet nº 41397, inscription. 1.^a C.I.F. - A28591287 - Registered office C/Princesa 29, 1º. 28008 Madrid. A subsidiary of LRQA Group Limited.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

LRQ/\



Certificate of Conformity of Factory Production Control No.: 0094/CPR/ MAD/20170149 ENG Schedule

Manufacturing plant Thickness: ≤ 120mm		Talleres Acesan, S.L.U. (ACESAN) Pol. Ind. Penapurreira, C/ Barosa, Parcela A-9.1 - 15320 As Pontes (A Coruña)	
			LRQA
	Execution class:	EXC3	_
			LRQA
04			
2 November 2023			LRQA
otified Body 0094			LRQ/A
	-	Pol. Ind. Penapurr 15320 As Pontes (Execution class: 04 2 November 2023	Pol. Ind. Penapurreira, C/ Barosa, Parcela A-9.1 - 15320 As Pontes (A Coruña) Execution class: EXC3 04 2 November 2023

Juan Antonio Pozo LRQA Decision maker



LRQA Inspection Iberia, S.A. is a company registered in the R. M. de Madrid, in Volume 5218 general, 4358, of Section Sec. 3.^a of the Companies Book, folio 133 sheet nº 41397, inscription. 1.^a C.I.F. - A28591287 - Registered office C/Princesa 29, 1º. 28008 Madrid. A subsidiary of LRQA Group Limited.

LRQA Group Limited, its affiliates and subsidiaries and their respective officers, employees or agents are, individually and collectively, referred to in this clause as 'LRQA'. LRQA assumes no responsibility and shall not be liable to any person for any loss, damage or expense caused by reliance on the information or advice in this document or howsoever provided, unless that person has signed a contract with the relevant LRQA entity for the provision of this information or advice and in that case any responsibility or liability is exclusively on the terms and conditions set out in that contract.

LRQ/\

I RQA